

FIG.1




FIG.2




FIG.3




FIG.4




FIG. 5




FIG. 6




FIG. 7




FIG.8




FIG.9A



FIG.9B




FIG.10




FIG. 11A




FIG. 11B




FIG. 12A




FIG. 12B




FIG. 13A




FIG. 13B






FIG. 14A




FIG. 14B




FIG. 15A




FIG. 15B




FIG. 16A




FIG. 16B




FIG. 17A




FIG. 17B




FIG. 17C




FIG. 18




FIG. 19




FIG.20




FIG. 21




FIG. 22




FIG. 23




FIG. 24






FIG. 25




FIG. 26




FIG. 27




FIG. 28




FIG.29




FIG.30




FIG.31




FIG.32




FIG. 33A




FIG. 33B




FIG. 34B




FIG. 34A




FIG.35




FIG. 36A




FIG. 36B




FIG. 37A




FIG. 37B






FIG.38A

FIG.38B




FIG.39A




FIG.39B




FIG.40A

FIG.40B

FIG.40C







FIG. 39C








FIG. 41C




FIG. 41D




FIG. 41E




FIG. 41F






FIG. 41G




FIG. 42A




FIG. 42B




FIG. 42C




FIG. 42D




FIG. 43A




FIG. 43B




FIG. 43C




FIG. 43D




FIG. 44A




FIG. 44B




FIG. 44C




FIG. 44D




FIG. 46A




FIG. 46B




FIG. 47A




FIG. 47B




FIG. 45




FIG. 47C




FIG. 47D




FIG. 47F




FIG. 47E






FIG. 48C




FIG. 48A




FIG. 48D




FIG. 48B




FIG. 49A




FIG. 49B




FIG. 50A




FIG. 50 B




FIG. 51A




FIG. 51B




FIG. 51C




FIG. 51D




FIG. 52A




FIG. 52B




FIG. 52C




FIG. 52D




FIG. 52E




FIG. 52F






FIG. 52G






FIG. 53C




FIG. 53D




FIG. 53E






FIG. 54A




FIG. 54B




FIG. 54C




FIG. 54D




FIG. 54E




FIG. 55A




FIG. 55B




FIG. 55C




FIG. 55D




FIG. 56A




FIG. 56B




FIG. 56C




FIG. 57A




FIG. 57B




FIG. 58A




FIG. 58B








FIG.59












FIG. 60E






FIG. 61C




FIG. 61D




FIG. 61E




FIG. 62A




FIG. 62B




FIG. 62C




FIG.63C

FIG.63B

FIG.63A




FIG. 64A






FIG. 64B






FIG. 65A




FIG. 66A




FIG. 67A




FIG. 68A




FIG. 65B



FIG. 66B




FIG. 67B




FIG. 68B






FIG. 69B




FIG. 69A




FIG. 70B




FIG. 70A




FIG. 71B




FIG. 71A




FIG. 72B




FIG. 72A




FIG. 73




FIG. 74A




FIG. 74C




FIG. 74B




FIG. 74D




FIG. 75A




FIG. 75B

2-PIECE HOUSING

SPRING

PLUNGER

BACK HOUSING

NOSE PIECE

ASSEMBLY

FIG. 76

